

U.S. Copper Porphyry Mines Report

THE TRACK RECORD OF WATER
QUALITY IMPACTS RESULTING FROM
PIPELINE SPILLS, TAILINGS FAILURES
AND WATER COLLECTION AND
TREATMENT FAILURES.

JULY 2012
(REVISED 11/2012)



EARTHWORKS™

U.S. COPPER PORPHYRY MINES:


The track record of water quality impacts resulting from pipeline spills, tailings failures and water collection and treatment failures.

EARTHWORKS, July 2012

(Revised 11/2012)

By Bonnie Gestring

Reviewed by Dave Chambers Ph. D.,
Center for Science in Public Participation (CSP2)




Photos, top to bottom:

Yankee Doodle tailings pond by Ecoflight
Chino Mine by Gila Resource Information Project (GRIP)
Sierrita Mine by Ecoflight
Bird fatality at Tyrone Mine by Jim Kuipers

Table of Contents

| | |
|---|----|
| Introduction, Methods, & Results | 4 |
| Conclusion | 5 |
| Table 1: Copper production amounts for mines reviewed in the report | 6 |
| Table 2. Synopsis of pipeline spills, tailings spills and impoundment failures, and water capture and treatment failures for 14 copper porphyry mines (1986-2012)..... | 7 |
| Case Studies of Active U.S. Copper Porphyry Mines | |
| Morenci Mine, AZ..... | 8 |
| Bingham Canyon, UT | 10 |
| Ray Mine, AZ | 12 |
| Chino Mine, NM..... | 15 |
| Bagdad Mine, AZ | 17 |
| Sierrita Mine, AZ | 18 |
| Pinto Valley Mine, AZ | 20 |
| Mission Complex, AZ | 22 |
| Robinson, NV..... | 23 |
| Tyrone, NM | 24 |
| Miami, AZ..... | 26 |
| Silver Bell, AZ..... | 27 |
| Mineral Park, AZ..... | 28 |
| Continental Pit, MT | 29 |
| References | 30 |



INTRODUCTION:

The Pebble Mine is proposed for development at the headwaters of the Bristol Bay watershed in southwest Alaska, which supports the world's largest wild sockeye salmon fishery. According to current ore estimates, the Pebble Mine would be the largest copper porphyry mine in the U.S., if constructed.

Currently, the U.S. Environmental Protection Agency (EPA) is completing a watershed assessment to evaluate the potential impacts of large-scale mining on water quality and fishery resources using a mine scenario that reflects the expected characteristics of mining operations at the Pebble deposit.

The purpose of this report is to compile the record of pipeline, seepage control and tailings impoundment failures at operating copper porphyry mines in the U.S., and to document associated water quality impacts.

Copper porphyry is a form of copper deposit that is often characterized as low-grade, typically with 0.4% and 1.0% concentration of copper, and containing other minerals such as gold, molybdenum, and other trace elements in the ore body. Copper porphyry deposits are almost always mined in industrial-scale open pit operations.

Contact water drainage from porphyry deposits commonly has concentrations of aluminum, cadmium, copper, iron, manganese, lead, and zinc that exceed US drinking-water limits, which were developed to protect public health, and also commonly exceeded for cadmium, copper, lead and zinc aquatic life standards, developed to protect fish and other sensitive aquatic organisms.¹

METHODS:

We reviewed state and federal documents and a federal database for fourteen copper porphyry mines currently operating in the U.S. with respect to three failure modes: pipeline spills or other accidental releases, tailings spills or tailings impoundment failures, and failure to capture and treat mine seepage.

The 14 mines represent 87% (14 out of 16) of currently operating copper porphyry mines, and 89% of U.S. copper production in 2010 – the most recent data on copper production available from the U.S. Geological Survey. The mines were chosen based on an operating record of more than five years. These mines provide a representative view of the types of environmental impacts resulting from the development of copper porphyry deposits, focusing on pipeline spills, tailings failures, and water collection and treatment failures.

RESULTS:

Our research shows that copper porphyry mines are often associated with water pollution associated with acid mine drainage, metals leaching and/or accidental releases of toxic materials. We found that all of the mines experienced at least one failure, with most mines experiencing multiple failures:

- At 14 of the 14 mines (100%), pipeline spills or other accidental releases occurred. The most frequent spills were reported at the Ray Mine in Arizona, where over fifty pipeline spills occurred from 1988 to 2012. Examples of recent pipeline spills include a 2012 spill at the Ray Mine which washed tailings into the Gila River, and a 2008 pipeline spill at the Morenci Mine of 186,000 gallons of sulfuric acid along two miles of Chase Creek - a tributary of the San Francisco River.
- At 13 of the 14 mines (92%), water collection and treatment systems have failed to control contaminated mine seepage, resulting in significant water quality impacts. The development of acid mine drainage was associated with the most severe and lasting impacts. For example, at the Tyrone and Chino mines – the two largest copper porphyry

mines in New Mexico, seepage from tailings impoundments and waste rock piles have resulted in surface and/or groundwater pollution. The State of New Mexico and U.S. Department of Justice have filed natural resource damage claims against the company for damages to water, fish and wildlife resources.

- At 4 out of 14 mines (28%), partial tailings impoundment failures have occurred, and at 9 out of 14 mines (64%), tailings spills have occurred. These included a 1997 partial failure of the tailings impoundment at the Pinto Valley Mine, where 8.1 acres of creek bed and surrounding upland were buried under material as deep as 42 feet. In 1993, heavy precipitation caused the Gila River to flood and breach the tailings impoundment at the Ray Mine, carrying pollutants 11 miles downriver. And in 1980, 2.6 million cubic yards of tailings were released at the Tyrone mine, and flowed 8 kilometers downstream.

CONCLUSION:

Our research shows that water quality impacts to surface and/or groundwater are common at currently operating copper porphyry mines in U.S., resulting from three failure modes (pipeline spills or other accidental releases, failure to capture and treat mine seepage, and tailings spills or impoundment failures).

These failures resulted in a variety of environmental impacts, such as contamination of drinking water aquifers, contamination and loss of fish and wildlife and their habitat, and risks to public health. In some cases, water quality impacts are so severe that acid mine drainage will generate water pollution in perpetuity.

This research demonstrates that the three failure modes identified in the Bristol Bay watershed assessment with respect to risks to water quality are reasonable and well-supported by the track record of operating copper porphyry mines in the U.S.

Many of the currently operating copper porphyry mines are located in the arid southwest, where precipitation is limited, and communication between surface and groundwater resources is limited. While beyond the scope of the analysis in this report, more significant impacts could be expected at mines in wetter climates, with abundant surface water and shallow groundwater, such as is the case in the Bristol Bay region. Research shows that mines with high acid generating potential and in close proximity to surface and groundwater are at highest risk for water quality impacts.²

Table 1**2010 copper production amounts for mines reviewed in this report.**

| Mine | Location | Company | 2010 Copper production (Metric Tons) |
|------------------------------|----------|---------------------|--------------------------------------|
| Bingham Canyon | UT | Kennecott/Rio Tinto | 250,000 ³ |
| Morenci | AZ | Freeport | 233,146 ⁴ |
| Ray | AZ | ASARCO | 105,051 ⁵ |
| Bagdad | AZ | Freeport | 92,079 ⁶ |
| Mission | AZ | ASARCO | 83,415 ⁷ |
| Sierrita | AZ | Freeport | 66,678 ⁸ |
| Robinson | NV | Quadra | 49,400 ⁹ |
| Tyrone | NM | Freeport | 37,194 ¹⁰ |
| Silver Bell | AZ | ASARCO | 21,000 ¹¹ |
| Chino | NM | Freeport | 15,400 ¹² |
| Mineral Park | AZ | Mercator | 14,605 ¹³ |
| Miami | AZ | Freeport | 8,100 ¹⁴ |
| Pinto Valley | AZ | BHP | 6,000 ¹⁵ |
| Continental Pit | MT | Montana Resources | Not available |
| Total production of 13 mines | | | 982,068 |
| Total U.S. production | | | 1,100,000 |
| Percent of total production | | | 89% |

Table 2

Synopsis of pipeline spills, tailings spills and impoundment failures, and water capture and treatment failures for 14 copper porphyry mines (1986-2012).

| Mine | Number of reported pipeline spills and other accidental releases* | Water collection and treatment failures | Tailings dam failures | Affected surface and/or ground water |
|-----------------|---|---|-----------------------|--|
| Morenci | 21 | Yes | | San Francisco River, Gila River, Chase Creek, groundwater aquifer |
| Bingham Canyon | 28 | Yes | | 72 square mile plume of contaminated groundwater; fish and wildlife habitat in the Great Salt lake ecosystem |
| Ray | 54 | Yes | Partial | Mineral Creek, Gila River, groundwater aquifer |
| Chino | 10 | Yes | | Hanover/Whitewater Creek, contaminated groundwater will require water treatment in perpetuity |
| Bagdad | 7 | Yes | | Boulder Creek, Burro Creek, Butte Creek, Bridle Creek |
| Sierrita | 18 | Yes | | Demetrie Wash and its tributaries; groundwater aquifer including drinking water wells in Green Valley |
| Pinto Valley | 3 | Yes | Partial | Pinto Creek |
| Mission | 3 | Yes | Partial | Tributaries of the Santa Cruz River, groundwater aquifer |
| Robinson | 8 | Unknown | | 2.3 miles of downstream drainage bed |
| Tyrone | 7 | Yes | Partial | Mangas Creek, groundwater contamination will require water treatment in perpetuity |
| Mineral Park | 3 | Yes | | Groundwater aquifer and surface water |
| Miami | 8 | Yes | | Pinal Creek alluvial aquifer |
| Silver Bell | 3 | Yes | | Cocio Wash |
| Continental Pit | 2 | Yes | | Groundwater aquifer |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

CASE STUDIES:

| MORENCI MINE, AZ (Freeport McMoRan) | |
|--|--|
| The Morenci Mining District is located in southeastern Arizona, near the towns of Clifton and Morenci. It is located near the Gila River, the San Francisco River and Eagle Creek. | |
| Reports of pipeline failures and other accidental releases* | <p>2008: Report of pipeline spill releasing 186,000 gallons of sulfuric acid and heavy metals into a tributary (Chase Creek) of the San Francisco River, resulting in a \$150,000 settlement with the State of Arizona.¹⁶ The highly acidic material traveled downstream more than 2 miles. The pollutants in the discharge exceeded Arizona surface water quality standards for copper, zinc and pH in Lower Chase Creek.</p> <p>2007: Report of release of 1,200,000 gallons of pregnant leach solution released due to power failure.¹⁷</p> <p>2006: Report of release of 3,000 pounds of sulfuric acid from pipeline break.¹⁸</p> <p>2006: Report of 1,127 pounds of material from PLS pipeline.¹⁹</p> <p>2006: Report of release of rich electrolyte (acid content 1,057 pounds) from an underground process pipeline.²⁰</p> <p>2004: Report of release of 8,920 pounds of sulfuric acid and water from process pipeline due to failure of valve.²¹</p> <p>2001: Report of release of 6,350 pounds of sulfuric acid released from pipeline.²²</p> <p>2000: Report of release of 72,000 gallons of sulfuric acid released from pipeline.²³</p> <p>1998: Report of release of 66,200 pounds of sulfuric acid released from pipeline.²⁴</p> <p>1996: Report of release of unknown amount of pregnant leach solution spilled from pipeline, affecting Chase Creek, leading to San Francisco River.²⁵ At the time of report, 20 gpm were being released.</p> <p>1996: Report of release of 160,000 gallons of process solution spilled due to pipeline weld failure.²⁶</p> <p>1996: Report of release of 50,000 pounds of sulfuric acid spilled due to backhoe hitting pipeline.²⁷</p> <p>1996: Report of 12,435 pounds of sulfuric acid released from pipeline.²⁸</p> <p>1995: Report of 2,980 pounds of sulfuric acid released from pipeline.²⁹</p> <p>1994: Report of 203,400 gallons of raffinate released due to ruptured pipe.³⁰</p> <p>1994: Report of 5,400 pounds of sulfuric acid released due to fractured weld in pipeline.³¹</p> <p>1993: Report of unknown amount of copper sulfate released into San Francisco River due to storm event.³²</p> <p>1993: Report of 180,000 gallons of pregnant leach solution spilled due to plugged drain line, affected 1 acre.³³</p> <p>1992: Report of 2,500 gallons of electrolyte released.³⁴</p> <p>1992: Report of 15,000 pounds of copper sulfate spilled due to valve failure.³⁵</p> <p>1992: Report of 7,500 gallons of electrolyte spilled due to failure of pipeline weld.³⁶</p> |
| Water collection and treatment failures | <p>In 2012, the U.S. Dept of Justice and the State of Arizona released a consent decree which found that, "mine tailings exposed to air and precipitation released hazardous substances on the surface of the tailings or that can percolate through the tailings to groundwater." The consent decree found that, "releases of hazardous substances at or from the Morenci mine site have occurred and allege that such releases have caused injuries to natural</p> |

| | |
|--|--|
| | <p>resources at and in the vicinity of the site including surface water, sediments, soils, terrestrial habitats and terrestrial receptors.”³⁷ A financial settlement followed an investigation of natural resource injuries related to the release of hazardous substances into the environment from acid mine drainage and process solution, among other sources.</p> <p>The investigation found that the main ore minerals are sulfide minerals, which have resulted in the development of acid mine drainage. According to the report, “Surface water has been, and most likely continues to be, exposed to hazardous substances released from the Morenci Mine through a variety of pathways.”³⁸ Concentrations of hazardous substances measured in groundwater at the Morenci Mine and measured in the San Francisco and Gila Rivers downstream of the mine provide further indications that hazardous substances present in the source materials at the Morenci Mine have been released to the environment. The report found that “Concentrations of total and dissolved zinc have exceeded 1,000 ug/l in the Gila River and concentration of dissolved copper have exceeded 100 ug/l in the San Francisco River.”³⁹ Contaminated groundwater is also released to surface water via seeps and springs.⁴⁰</p> |
| <p>Tailings spills and impoundment failures</p> | <p>No impoundment failures.</p> |
| <p>Impacts to water, fish and wildlife</p> | <p>In 2012, the US Department of Justice and Department of Interior have jointly announced that Freeport McMoRan has agreed to pay \$6.8 million to settle federal and state natural resource damages related to the Morenci Mine. According to the complaint, the hazardous substance release, which included sulfuric acid and metals, injured, destroyed or led to the loss of “surface waters, terrestrial habitat and wildlife, and migratory birds.”⁴¹</p> <p>As described above, metals contamination occurred in the San Francisco and Gila Rivers downstream of the mine, and to groundwater supplies.</p> |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

BINGHAM CANYON MINE and SMELTER, UT (Kennecott)

The Bingham Canyon Mine is the deepest open pit mine in the world, located southwest of Salt Lake City, Utah.

| | |
|---|---|
| <p>Reports of pipeline failures and other accidental releases*</p> | <p>2011: Report of malfunction of equipment that allowed the release of approximately 145,424 gallons of copper tailings.⁴²</p> <p>2011: Report of pipeline overflow onto soil with estimated 100,000 – 290,000 gallons of copper tailings material released from pipeline.⁴³</p> <p>2011: Report of tailings slurry released from tailings slurry hot box. 160,000 gallons of tailings released.⁴⁴</p> <p>2010: Report of a release of process water due to broken pipeline.</p> <p>2010: Report of a discharge of sulfuric acid from a pipeline in the precious metal plant released between 4,000-5,000 gallons.⁴⁵</p> <p>2007: Report of a release of 35,000 gallons of hydromet tails containing arsenic due to pipeline break.⁴⁶</p> <p>2007: Report of 1,240,000 gallons of process water containing arsenic from pipeline break due to cold temperatures.⁴⁷</p> <p>2006: Report of 270,000 gallons of process water released because of pump failure, which resulted in overflow of containment area.⁴⁸</p> <p>2006: Report of 660,000 gallons of process water containing arsenic released due to cracked pipe.⁴⁹</p> <p>2006: Report of 1,000,000 gallons of process water released from the Magna Reservoir due to a failed level indicator.⁵⁰</p> <p>2004: Report of 4,000,000 gallons of process water with arsenic from pipeline.⁵¹</p> <p>2004: Report of 2,000,000 gallons of process water with arsenic from broken process water line.⁵²</p> <p>2004: Report of 202,000 gallons of process water released due to pipeline failure.⁵³</p> <p>2003: Report of 70,000 gallons of process water with arsenic released due to pipeline failure.⁵⁴</p> <p>2003: Report of 70 tons of copper concentrate released from pipeline.⁵⁵</p> <p>2003: Release of copper concentrate, containing 340 pounds of arsenic, 20,000 pounds of copper, and 200 pounds of lead.⁵⁶</p> <p>2003: Copper concentrate pipeline ruptured, releasing 240,000 tons of copper, 428 tons of arsenic, 253 tons of lead.⁵⁷</p> <p>2002: Report of 5,800 gallons of process water from slag pot cooling area due to plugged drain line.⁵⁸</p> <p>2001: Report of tailings pipeline failure, releasing 4 pounds of arsenic, 14 pounds of chromium and 1 pound of lead.⁵⁹</p> <p>2000: Report of 110 tons of ore slurry released due to a leak in ore line.⁶⁰</p> <p>2000: Report of 18,000 tons of sulfuric acid released from pipe due to flange failure.⁶¹</p> <p>1999: The process water pipeline sprung a series of leaks in 1989 and 1999. It has been estimated that 100 million gallons of process water with high arsenic levels spilled before the leak was discovered.⁶²</p> <p>1998: Report of copper sulfate released into a canal.</p> <p>1998: Report of clogged piping system causing pipe to back up and overflow releasing acid</p> |
|---|---|

| | |
|--|--|
| | <p>rock drainage into water.</p> <p>1997: Report of settling pond overflow due to clogged outlet valve. Release of copper sulfate into water.</p> <p>1997: Report of pipeline rupture releasing process water (pH 2.5-4.0) into water.</p> <p>1993: Report of 45,000 gallons of wastewater spilled due to a rupture of the transfer line.⁶³</p> <p>1991: Report of 30,000 gallons of industrial wastewater spilled at the wastewater treatment plant due to line break.⁶⁴</p> |
| <p>Water collection & treatment failure</p> | <p>2011: Noncompliance in April-June 2011 for discharges of copper, zinc and total suspended solids at copper smelter.⁶⁵</p> <p>Wastewater from the mine has escaped the site's collection system, contaminating groundwater with acid, metals and sulfates. The groundwater plume extends towards the nearby Jordan River and covers more than 72 square miles – rendering water for thousands of Salt Lake City residents undrinkable.⁶⁶ There have been multiple tailings spills.⁶⁷</p> <p>Drainage from the waste rock piles will require water treatment in perpetuity to prevent additional groundwater pollution.⁶⁸</p> <p>In February 2008, the United States Fish and Wildlife Service took legal action against Kennecott for the release of hazardous substances from the mine's facilities, including selenium, copper, arsenic, lead, zinc and cadmium.⁶⁹ Groundwater contaminated by mine operations has been released from the mine site through artesian springs into areas that serve as fish and wildlife habitats. According to the federal biologists, the release of these hazardous pollutants has harmed natural resources, including migratory birds and their support ecosystems, which includes wetlands, marshes, freshwater wildlife habitats, playas and riparian areas and freshwater ponds.⁷⁰</p> |
| <p>Impacts to water, fish and wildlife.</p> | <p>In February 2008, the United States Fish and Wildlife Service took legal action against Kennecott for the release of hazardous substances from the mine's facilities, including selenium, copper, arsenic, lead, zinc and cadmium.⁷¹ Groundwater contaminated by mine operations has been released from the mine site through artesian springs into areas that serve as fish and wildlife habitats. According to the federal biologists, the release of these hazardous pollutants has harmed natural resources, including migratory birds and their support ecosystems, which includes wetlands, marshes, freshwater wildlife habitats, playas and riparian areas and freshwater ponds.</p> |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

RAY MINE and HAYDEN SMELTER, AZ (ASARCO)

The Ray Mine is a copper mining facility of approximately 6,100 acres near Kelvin, Arizona which discharges into Mineral Creek, a tributary of the Gila River, and the Hayden Facility is a smelting facility located in Hayden Arizona along the Gila River.

| | |
|---|--|
| <p>Reports of pipeline failures and other accidental releases*</p> | <p>2012: Potable water line ruptured, which washed tailings into the Gila River.⁷²</p> <p>2007: A leak from a coupling in a tailings pipeline spilled tailings onto the banks and into the Gila River. A \$20,000 civil penalty was paid.⁷³ According to the report, the pipeline had been in use since the construction of “d” tailings impoundment (about 1985), was in good condition, and was visually inspected on a frequent basis. A support structure failed on Feb. 4, 2007, resulting in an angular deflection at one of the couplings, resulting in the tailings leak.⁷⁴</p> <p>2007: Report of 1,000 pounds of sulfuric acid spilled from pipeline.⁷⁵</p> <p>2006: Report of 600 gallons of sulfuric acid spilled due to piping failure inside of mine.⁷⁶</p> <p>2000: Report of 80.95 pounds of copper sulfate released from basin/dam into Mineral Creek.⁷⁷</p> <p>2000: Report of 200 gallons of copper sulfate spilled from pipe.⁷⁸</p> <p>1999: Report of 33,000 gallons of tailings water released from pipeline.⁷⁹</p> <p>Between August 1988 and November 1997, 47 separate releases of hazardous substances into Mineral Creek from the Ray Mine were reported.⁸⁰</p> <p>According to a 2012 ecological risk assessment prepared by the State of Arizona, “A large portion of these releases were uncontained and eventually entered Mineral Creek and the Gila River. Hazardous chemicals released included copper sulfate, copper tailings and leachate.”⁸¹ In addition, the report found that multiple groundwater wells downgradient of the Ray Mine were found to be highly contaminated by a common leachate solution which was attributed to releases to shallow groundwater along Mineral Creek, and it concluded that “it is likely that the hazardous substances present in shallow groundwater will represent an ongoing source of chronic contamination to Mineral Creek (Lipton 2009).”⁸²</p> <p>According to a report by the U.S. EPA, at least 19 spills of hazardous materials were reported at the Ray Mine from August 1990 through November 1993.⁸³ The majority of spills were from dams, pipelines, and ponds. The discharges typically resulted from either accidental discharges associated with heavy rain or from chronic seepage from leaching facilities into the ground water, which then entered the creek. The report found that, “surface water quality has been significantly affected.” A total of 41 violations of total copper, dissolved copper, and beryllium numeric surface water quality standards were documented by the Arizona Department of Environmental Quality (ADEQ), EPA, and ASARCO in Mineral Creek below the Ray Mine.⁸⁴</p> <p>According to the report, “Arizona’s Department of Game and Fish believes that the discharges from the Ray Unit have negatively affected both the water quality and the aquatic life of Mineral Creek. The Department conducted a biosurvey of Mineral Creek in July 1993. In a report dated September 30, 1993, the Department found that although the numbers and diversity of aquatic insects and fish were high above the Ray Unit, an almost complete absence of aquatic life at sampling stations was observed directly downstream of the mine.”⁸⁵</p> |
| <p>Water collection and</p> | <p>According to an EPA report, “The mine’s routine operations are chronically affecting the quality of both surface and ground waters in the mine’s vicinity.”⁸⁶ According to the report, the Arizona Dept. of Environmental Quality reported in 1996 that approximately</p> |

| | |
|--|--|
| <p>treatment failures</p> | <p>one-half mile of the Mineral Creek streambed below the Ray Mine was visibly affected by mine activities. The streambed was coated with a blue-green layer of copper oxides.⁸⁷</p> <p>In April 1995, EPA reported that six ground water wells situated downgradient of the electrowinning plant and the electrowinning dam were continuously pumping PLS.⁸⁸ Multiple groundwater wells were found to be highly contaminated by a common leachate solution which was attributed to releases by ASARCO into shallow groundwater along Mineral Creek. It concluded that it is likely that the hazardous substance present in shallow groundwater will represent an ongoing source of chronic contamination to Mineral Creek (Lipton 2009).⁸⁹</p> |
| <p>Tailings spills and impoundment failures</p> | <p>2012: Seepage from the tailings impoundment was released into two catch basins and into a tributary of the Gila River.⁹⁰ At the time of the report, seepage into the tributary was estimated at 75 gpm. The incident occurred as a result of operator error during the initiation of a new upstream construction method at its Elder Gulch Tailings Impoundment in 2011.⁹¹ A delay in the completion of the tailings distribution line resulted in the uneven distribution of the tailings, which in turn caused the ponded water to migrate, and eventually be released from the impoundment into drainages. The seep was discovered on January 30, 2012, and seep flow from the embankment was observed to have stopped on February 7, 2012.</p> <p>2011: A report of 6,000-8,000 tons of copper ore tailings released from one of the tailings pond due to a breach in the dike.⁹² The company failed to operate and maintain all listed permitted facilities in its Aquifer Protect Permit No. P-100507 to prevent the unauthorized discharge of copper ore tailings.⁹³</p> <p>In 1993, heavy precipitation caused the Gila River to flood, and breach the AB-BC tailings impoundment containment dike.⁹⁴ According to a report by the U.S. EPA, "Continued flooding over the next several days resulted in a total of 13 separate breaches of the dike, three of which eroded through the dike and into the toe of the tailings pile. The total discharge was approximately 292,000 tons of tailings, which was about 216,000 cubic yards of material."⁹⁵ It also found that sampling of the river showed that elevated concentrations of pollutants occurred at least 11 miles downstream of the spill. The tailings formed bank and bottom deposits in the river, impairing both recreational uses and the quality of habitat for plants and animals.⁹⁶</p> |
| <p>Impacts to water, fish and wildlife</p> | <p>In April 2009, the Department of the Interior and the State of Arizona, acting as natural resource trustees (Trustees) received a monetary settlement and three parcels of land from ASARCO, L.L.C. through the Natural Resource Damage Assessment and Restoration (NRDAR) program to account for injuries to trust resources incurred through multiple releases of hazardous substances by ASARCO L.L.C. into Mineral Creek and the Gila River in Pinal County, Arizona.⁹⁷</p> <p>According to a 2012 ecological risk assessment by the State of Arizona, "The site of injury stretches from the Ray Mine and the Hayden Facility, to the Gila River from the Ashurst-Hayden Diversion Dam, upstream past the confluence of the San Pedro and Gila Rivers, and for a distance of 5 miles up each of those rivers beyond the confluence and to Mineral Creek from its confluence with the Gila River upstream to a point one mile above the Big Box Canyon Dam." The most substantial injuries occurred in the reach of Mineral Creek that extends from the tunnel outlet to the Gila River. The report finds that, "Dissolved copper concentrations in the surface water of this reach have been recorded up to 130 times surface water quality standards that will sustain aquatic life, and sediment copper concentrations have been recorded to exceed up to 22 times the level beyond which injury is inflicted on sediment-dwelling organisms (MacDonald et al. 2000)." These concentrations of copper caused a complete loss of aquatic life in this reach.⁹⁸</p> <p>Overall, the report found that, "ecosystem services lost in the 117 acres that include Mineral Creek and its associated riparian habitat were estimated to be 100% from 1981-</p> |

| | |
|--|--|
| | 2005, and up to 50% from 2005 to the present (Lipton 2009). Hazardous releases also affected the aquatic and riparian portions of the Gila River near the Ray Mine/Hayden Smelter Complex, including approximately 2,930 acres upstream of Mineral Creek to the confluence with the San Pedro River, and approximately 1,620 acres downstream of Mineral Creek to the Ashurst-Hayden Dam. The most substantial loss of ecosystem services in these areas occurred during the three years following the release of 300,000 tons of tailings in 1993, when ecosystem service losses were estimated at 10-25% (Lipton 2009).” ⁹⁹ |
|--|--|

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

CHINO MINE, NM (Freeport McMoRan)

The Chino Mine is located approximately 12 miles southeast of Silver City, New Mexico. The site is east of the Continental divide and drains into ephemeral drainages in the Mimbres watershed.

| | |
|---|--|
| <p>Reports of pipeline failures and other accidental releases*</p> | <p>2007: A spill involving one million gallons of acidic mine waters overflowed a containment sump into a storm water diversion channel and traveled more than two and a half miles down a surface water tributary near the mine. The spill resulted in groundwater contamination and a settlement of \$276,000 was reached with the State of New Mexico.¹⁰⁰</p> <p>Multiple other tailings spills have occurred, which are listed below:¹⁰¹</p> <p>2000: Report of 480,000 gallons of tailings slurry discharged, with 93,000 gallons entering Whitewater creek.</p> <p>1999: Report of 3.25 million gallons of tailings spilled into Whitewater Creek.</p> <p>1997: Report of 100,000 gallons of tailings spilled into Whitewater Creek.</p> <p>1996: Report of 152,000 gallons of liquid tailings spilled into Whitewater Creek.</p> <p>1993: Report of 208 tons and 91,500 gallons of tailings accidentally released to Whitewater Creek in six separate incidents resulting from the rupture of degraded pipes.</p> <p>1992: Report of 120,000 gallons of tailings spilled into a basin.</p> <p>1991: Report of 3,200 gallons of tailings released into Whitewater Creek when a tailings pipeline ruptured.</p> <p>1988: Heavy rains led to the release of 180 million gallons of acidic wastewater into Whitewater Creek over a 35-day period. Analysis of the wastewater indicated that it had 30 times the allowed levels of the hazardous substance cadmium, as well as more than 30 times the allowed levels of sulfates.¹⁰²</p> <p>Enlargement of the precipitation plant reservoir was completed in 1985 to prevent overflows of leachate solution into Whitewater Creek. Above average precipitation however caused the new reservoir to overflow and discharge waters to Whitewater Creek on October 9 and 10, 1985; May 6, 1986 and October 6, 1986.¹⁰³</p> |
| <p>Water collection and treatment failures</p> | <p>In 2011, the U.S. Department of Justice and State of New Mexico issued a consent decree for damages to natural resources from hazardous substances from the Chino, Tyrone and Cobre mines.¹⁰⁴ The settlement followed an investigation of natural resource injuries related to the release of hazardous substances into the environment from acid mine drainage and process solution, among other sources.</p> <p>It found that, "surface water and associated sediments are exposed to hazardous substances released from the Chino Mine through a variety of pathways, including leaks and spills of process water, tailings spills; runoff, and infiltration or percolation from tailings and waste stockpiles."¹⁰⁵ Groundwater contamination from tailings pond #7, which became active in 1988, has occurred to the east, west and south of impoundment.</p> <p>It also found that hazardous substances have been released into groundwater at the Chino mine from multiple source areas.¹⁰⁶ Concentrations of hazardous substances in groundwater in exceedance of water quality standards confirm release to groundwater throughout the Chino Mine. Groundwater flow modeling for the North Mine area indicates that contaminated groundwater in four of these areas is not captured by dewatering in the main pit.</p> <p>In the South Mine area, groundwater has exceeded standards for manganese and cadmium at Middle Whitewater Creek, Hurley and Lake One, and has exceeded standards for copper at Lake One.¹⁰⁷</p> |

| | |
|---|---|
| | A 2012 assessment of groundwater impacts concluded that contaminated seepage from the mine will require water treatment in perpetuity. ¹⁰⁸ |
| Tailings spills and impoundment failures | Tailings spills (see above). |
| Impacts to water, fish and wildlife | <p>The 2003 ecological risk assessment reported elevated concentrations of the hazardous substances copper and zinc in surface water from five different drainages at the Chino Mine, including Hanover/Whitewater Creek, Bayard Canyon, Bolton Draw, the unnamed drainage between Bolton Draw and Lampbright Draw and Lampbright Draw.¹⁰⁹</p> <p>The areal extent of injured alluvial and regional groundwater at the Chino Mine is 13,935 acres.¹¹⁰</p> <p>According to the closure plan for the Chino Mine, contaminated groundwater will require water treatment in perpetuity.¹¹¹</p> |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

BAGDAD MINE, AZ (Freeport McMoRan)

The Bagdad Mine is an open pit copper and molybdenum complex 100 miles northwest of Phoenix, Arizona.

| | |
|---|---|
| <p>Reports of pipeline failures and other accidental releases*</p> | <p>2009: Report of a broken pipeline causing a release of 2,378,500 gallons of sulfuric acid.¹¹²</p> <p>2007: Report of 22,500 gallons of raffinate solution containing sulfuric acid spilled from a pond.¹¹³</p> <p>2004: Report of 7,484 pounds of sulfuric acid released due to malfunction of pipe.¹¹⁴</p> <p>2004: Report of 354 pounds of sulfuric acid released due to crack in pipe.¹¹⁵</p> <p>1999: Report of 12,000 gallons of process water with residual chlorine spilled into Bridle Creek.¹¹⁶</p> <p>1997: Report of 1,500 pounds of sulfuric acid due to pipeline failure.¹¹⁷</p> <p>1997: Report of 7,200 pounds of sulfuric acid overflowed from pond due to drain blockage.¹¹⁸</p> |
| <p>Water collection and treatment failures</p> | <p>In 1996, the EPA and the state of Arizona announced that Cyprus Bagdad Copper Corp., a subsidiary of Cyprus Mineral Corp., paid penalties totaling \$760,000 for discharging contaminated water from the Bagdad Copper Mine.¹¹⁹ The discharges involved various facilities including tailings ponds, leach dumps, and a sewage treatment plant, but by far the major discharges came from the Copper Creek Leaching Basin, in which acidic, copper-tainted underground seepage entered Boulder Creek.¹²⁰</p> <p>According to an EPA report, seepage of pregnant leach solution from the Copper Creek Leaching System was discovered in a receiving pool in Boulder Creek in 1991.¹²¹ Studies indicated that instead of being contained by the Copper Creek Flood Basin, the heavily contaminated solution seeped under the dam. The concentration of total copper in samples collected in the pool in Boulder Creek were as high as 76.4 mg/l. On March 29, 1993, U.S. EPA issued a Finding of Violation and Order against Cyprus.¹²²</p> <p>According to a 2006 study that compared the water quality predictions made during mine permitting with water quality impacts during operations, although no water quality impacts were predicted during the permitting process, the following water quality violations occurred: Water quality monitoring (1998-2002) in Boulder Creek, found water quality exceedances for arsenic, lead, mercury, and selenium. In Burro Creek, there were water quality exceedances for copper and mercury. In Butte Creek, there were water quality exceedances for mercury and selenium.¹²³</p> |
| <p>Tailings impoundment spills and/or failures</p> | |
| <p>Impacts to water, fish and wildlife</p> | <p>Copper and low pH releases to ground and surface waters, hazards to aquatic life from solution releases beneath and over containment system dam. Water quality impacts to Boulder Creek, Burro Creek and Butte Creek.</p> |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

SIERRITA MINE, AZ (Freeport McMoRan)

The Sierrita Mine is an open pit copper and molybdenum mining complex 20 miles southwest of Tucson, Arizona.

| | |
|---|--|
| <p>Reports of pipeline failures and other accidental releases*</p> | <p>2011: Report of 849 gallons of sulfuric acid spills from a pipeline leak.¹²⁴</p> <p>2008: Report of 1,100 gallons of sodium hypochlorite spilled due to loose pipe.¹²⁵</p> <p>2005: Report of 1,000 pounds of sulfuric acid from a broken pipeline.¹²⁶</p> <p>2005: Report of 8,058 pounds of sulfuric acid released from a broken pipeline.¹²⁷</p> <p>2002: Report of 39,375 pounds of sulfuric acid spilled from a pipeline due to a separated flange.¹²⁸</p> <p>2001: Report of 1,209 pounds of sulfuric acid spilled from pipeline.¹²⁹</p> <p>2000: Report of 5,350 gallons of leach solution spilled from pipe.¹³⁰</p> <p>1998: Report of 160,000 gallons of mill tailings spilled into water due to overflow resulting from power failure.¹³¹</p> <p>1998: Report of 40,000 gallons leach solution spilled from pipeline.¹³²</p> <p>1998: Report of 120,000 gallons of leach solution spilled from pipeline.¹³³</p> <p>1997: Report of 2,798 pounds of sulfuric acid spilled due to pipeline rupture.¹³⁴</p> <p>1997: Report of release of 8,000 pounds of sulfuric acid due to pipe joint failure.¹³⁵</p> <p>1996: Report of release of 3,000 gallons of sulfuric acid due to pipeline failure.¹³⁶</p> <p>1994: Report of another pipeline break allowed a discharge into Demetrie Wash of approximately 120,000 gallons of reclaim water.¹³⁷</p> <p>1994: Report of approximately 5,000 gallons of reclaim water were released as a result of a pipeline break.¹³⁸</p> <p>1993: Report of a leak in a pipeline transporting process water discharged approximately 200,000 gallons of a mixture of process wastewater and storm water run-off to an unnamed tributary of Demetrie Wash.¹³⁹</p> <p>1993: Report of Cyprus Sierrita discharging approximately 2,700,000 gallons into the same wash as a result of another pipeline break.¹⁴⁰</p> <p>1993: Report of approximately 450,000 gallons released to the wash in October 1993 by a broken pipeline.¹⁴¹</p> |
| <p>Water collection and treatment failures</p> | <p>From the summer of 1992 until December 1994, Sierrita discharged contaminated process water and storm water run-off to Demetrie Wash and its tributaries from various overflows, seepages, and pipeline leaks and breaks.¹⁴²</p> <p>In 1996, the U.S. Department of Justice issued a civil claim against Cyprus Sierrita on behalf of the State of Arizona and the U.S. pursuant to the Clean Water Act.¹⁴³ Cyprus Sierrita entered into a Consent Decree to pay a penalty of \$88,000 for numerous violations.</p> <p>According to a 2011 report, seepage from an unlined tailings pond at the Sierrita mine has sent a plume of contaminated groundwater toward the city of Green Valley, causing drinking water wells to record high levels of sulfates.¹⁴⁴</p> <p>In 2006, the company signed a mitigation order on consent with the State of Arizona to address sulfate in drinking water. It requires the company to develop a mitigation plan to be submitted in 2009.</p> |
| <p>Impacts to</p> | <p>Ground water and surface water contamination have occurred from pipeline leaks and breaks, overflows, and underground seepage from process wastewater, wastewater, and</p> |

| | |
|---------------------------------|--|
| water, fish and wildlife | storm water surface impoundments. Drinking water wells have been affected. |
|---------------------------------|--|

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

PINTO VALLEY MINE, AZ (BHP Billiton)

The Pinto Valley Mine is an open pit copper and gold mine located about 126 km east of Phoenix, AZ.
Formerly owned by Magma Copper Company.

| | |
|--|--|
| <p>Reports of pipeline failures and other accidental releases</p> | <p>2010: Report of a storm event, which caused 5,362 tons of tailings to spill onto soil and Pinto Creek, including 214 pounds of arsenic and 11 pounds of lead.¹⁴⁵ 500 cubic yards were released into water. Pinto Creek is a tributary to Roosevelt Lake.</p> <p>2010: Report of an unknown amount of mine tailings released onto land, with a potential release to water, due to heavy rains.¹⁴⁶</p> <p>2007: A release of impounded storm and seepage water occurred due to a flange separation in a tailings line. The unexpected release washed out a section of the secondary containment, which allowed it to escape. An estimated 45,000 gallons of water (stormwater and tailings seepage) reported to an unnamed tributary to Pinto Creek.¹⁴⁷</p> <p>2001: Report of 1,725 pounds of sulfuric acid released due to pipeline break.¹⁴⁸</p> |
| <p>Water collection and treatment failures</p> | <p>According to a 2001 EPA report, a portion of Pinto Creek from its headwaters to Spring Creek was first listed as water quality limited in 1992 based on elevated copper concentrations and pH values that were related to discharges from the Pinto Valley and another mine. The remaining portions of the stream were added to the 303(d) list in 1994.¹⁴⁹</p> <p>The report further states that, "Since 1989, extreme storm events caused releases of copper bearing sediments and liquids to Pinto Creek from Pinto Valley operations. These releases resulted from partial tailings dam failures, pipeline breaks, seepage flows, conveyance blockages, and storm water overflows. Recent significant release events occurred in August 1989, July 1990, January 1991, August to September 1991, January to February 1993, and October 1997. In each of these events, materials were released in quantities sufficient to impact Pinto Creek or its tributaries."¹⁵⁰</p> <p>Based on EPA's review of discharge monitoring reports between January 1990 and September 1991, Magma (now Pinto Valley) reportedly discharged effluent to Pinto Creek or its tributaries in excess of allowable effluent limitations on numerous occasions, and/or did not collect and analyze samples, in violation of permit conditions.¹⁵¹</p> <p>According to the report, during the first episode, approximately 3,000 gallons of effluent containing total suspended solids and copper of unknown concentrations was discharged from the ditch. A similar discharge of 24,000 gallons occurred on September 5, 1991. An estimated 39,000 gallons of effluent in exceedance of Arizona Surface Water Quality Standards and Aquifer Water Quality Standards for copper, zinc, and lead were discharged from the ditch on September 23, 1991.¹⁵²</p> |
| <p>Tailings spills or failures</p> | <p>In 1997, a partial tailings failure deposited an estimated 276,000 cubic yards of tailings in Pinto Creek.¹⁵³ It buried 8.1 acres of creek bed and surrounding upland with material as deep as 42 feet.¹⁵⁴</p> <p>Another incident occurred in 1993, when heavy rainfall overwhelmed the mine's water management capabilities. During the rainfall event, a reservoir overflowed the tailings pile, tore out a levee, and carried tailings to Pinto Creek.¹⁵⁵ In addition, a retention pond that held storm water and mineral wastes discharged material into the creek after its dam was breached. According to an EPA report of the incident, "Critical water containment structures in place at the mine in 1992 were reportedly designed to hold a 100-year, 24-hour storm event. Nonetheless, the mine discharged hundreds of tons of tailings and millions of gallons of contaminated water into Pinto Creek."¹⁵⁶ Water quality sampling during January and February 1993 indicated 286 exceedances of daily and monthly water quality parameters. Fish surveys collected before and after the discharges showed a</p> |

| | |
|---|---|
| | <p>marked decline in populations of the desert sucker (<i>Pantosteus clarki</i>) following the discharges. Although they were abundant in 1992, a summer survey in 1993 found only one adult in Pinto Creek.¹⁵⁷</p> <p>In January 1991, the face of Tailings Dam No. 3 failed, releasing 150 - 250 tons of tailings into Pinto Creek, and two million gallons of water.¹⁵⁸</p> <p>In March 1991, another large quantity of tailings was released from the same pile.¹⁵⁹ This release occurred from an over-saturation of the tailings face benches due to heavy precipitation, and an estimated 3.4 million gallons of water also were discharged.</p> |
| <p>Impacts to water, fish and wildlife</p> | <p>Extensive impacts to surface water quality and fish habitat in Pinto Creek resulting from tailings spills, and other mine related impacts.</p> |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

MISSION COMPLEX MINE, AZ (ASARCO)

The Mission Mine complex is an open pit copper mine and underground copper mine located near Sahuarita, Arizona (18 miles south of Tucson). The Mine covers approximately 29.7 square miles, and a portion of the mine occupies tribal lands.

| | |
|--|---|
| Reports of pipeline failures and other accidental releases* | <p>2011: Report of a backup of a tailing line resulting in release of tailings into a dry wash.¹⁶⁰</p> <p>2002: A violation involving the discharge of primarily copper laden stormwater runoff and process water discharge to ephemeral tributaries of the Santa Cruz river near Tucson in violation of the facilities Multi Sector General Permit Case # 09-2002-0064.</p> <p>2001: Report of a 36-inch distribution tailings line releasing 200 tons of tailings into a dry stream channel.¹⁶¹</p> |
| Water collection and treatment failures | <p>According to EPA fact sheet released in 2008, discharges from mine (outfall 001A) contain significant levels of copper and lead, and TSS, which have been out of compliance since October, 2003.¹⁶² Outfalls from the Mission complex discharge to ephemeral streams that are tributaries to the Santa Cruz River.</p> <p>Three large tailings ponds and several mine dumps are located on land leased from the Indian landowners approximately 1 mile south of the Arroyos project area. According to a report by the Bureau of Reclamation, leachate from these tailings has contributed to elevated levels of sulfate, TDS, and hardness in the aquifer below and adjacent to the ponds.¹⁶³</p> |
| Tailings spills or impoundment failures | <p>The Bureau of Reclamation Report also states that, "Surface drainage from a break in a tailings pond dike in 1990 released large volumes of material into wash complexes that drain toward the SCR."¹⁶⁴</p> |
| Impacts to water, fish and wildlife | <p>Ground and surface water pollution.</p> |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

| | |
|--|---|
| <p>ROBINSON MINE, NV (Robinson Nevada Mining Co.) Formerly owned by BHP Copper, Magma Nevada Mining Company The Robinson Mine is an open pit copper and gold mine located in eastern Nevada approximately 11 km west of Ely, Nevada.</p> | |
| <p>Reports of pipeline failures and other accidental releases*</p> | <p>1996: The mine experienced eight reported spills during 1996. Most of these spills involved tailings solution and reclaim water releases due to equipment failures. The five spills resulting in releases of copper flotation tailings had spill volumes ranging from 1,500 gallons to 66,000 gallons. Four of these spills resulted in contamination of relatively small areas of soil. The largest spill resulted in contamination of a downstream drainage bed for 2.3 miles with an average flow path width of 3 ft. Two spills resulted in a combined release of 76,000 gallons of reclaim water.¹⁶⁵</p> |
| <p>Water collection and treatment failure</p> | <p>In 2010, the State of Nevada issued a Finding of Alleged Violation and Order for the failure to comply with permit and regulatory requirements regarding stabilization of spent ore and associated acid rock drainage at the Intera and Green Springs area.¹⁶⁶</p> <p>The Order requires the mine to “submit a plan by May 11, 2010 stating whether the Mill-Water Ponds, the overhead standpipe near the Mille-Water Ponds, and any other leaking pipes or tanks in the area, will remain on the Liberty Dump or be moved off the Liberty Dump (and any other potential sources). If the Mill-Water Ponds will remain on the Liberty Dump, specify whether they will be replaced, or tested and repaired to demonstrate integrity of primary and secondary liners. If the ponds will be tested and repaired to demonstrate integrity, include a complete description of the proposed methods to be used for NDEP review and approval.”</p> |
| <p>Tailings spills and impoundment failures</p> | <p>Tailings spill (see above)</p> |
| <p>Impacts to water, fish and wildlife</p> | <p>Contamination of downstream drainage bed for 2.3 miles from mine tailings process water. (See above)</p> |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

TYRONE MINE, NM (Freeport McMoRan)

The Tyrone Mine is located approximately 10 miles southwest of Silver City, New Mexico.
The mine straddles the Continental Divide.

| | |
|---|--|
| <p>Reports of pipeline failures and other accidental releases*</p> | <p>2006: Report of a spill occurring when a CTI tanker truck loaded with about 3,000 gallons of acid collided with a pickup truck, spilling about 500 gallons of the acid on the highway and adjacent property.¹⁶⁷ (non pipeline)</p> <p>2003: Report of approximately 2,600 gallons of 16% sulfuric acid solution spilled at the Tyrone mine during maintenance activity on a pipeline system.¹⁶⁸</p> <p>2001: Report of 500-1000 gallons of solution leaked from the pipeline.¹⁶⁹</p> <p>2001: Report of 300 gallon spill of raffinate and organic solution from pipeline.</p> <p>2001: Report of 150 gallon spill from the Seep 5# pond, which overflowed with 75 gallons entering Deadman Canyon. Seepage had a pH of 4 and Deadman Canyon was flowing at approximately 50 gpm at the time.¹⁷⁰</p> <p>1997: Report of 65,000 gallons of raffinate leaked from a ruptured weld in a raffinate pipeline.¹⁷¹</p> <p>1997: Report of a transfer line rupture due to cold weather.</p> <p>1994: Report of No. 2 diesel fuel oil from two broken pipes detected in groundwater.¹⁷²</p> <p>2012 report identifies diesel fuel contaminant concentrations in groundwater from a leak in distribution pipeline at diesel tank farm, which migrated to regional aquifer.¹⁷³</p> |
| <p>Water collection and treatment failures</p> | <p>In 2011, the U.S. Department of Justice and State of New Mexico issued a consent decree for damages to natural resources from hazardous substances from the Tyrone, Chino, and Cobre mines.¹⁷⁴</p> <p>The settlement followed an investigation of natural resource injuries related to the release of hazardous substances into the environment from acid mine drainage and process solution, among other sources.¹⁷⁵ According to the investigation, “groundwater in both the regional aquifer and the perched groundwater aquifers at the site have been exposed to hazardous substances through a variety of pathways.”¹⁷⁶ The assessment at the Tyrone Mine identified 14 different mine area sources that have affected water quality, including seepage from tailings impoundments, leach stockpiles and waste rock stockpiles.</p> <p>A 2012 groundwater assessment concluded that contaminated seepage from the mine will require water treatment in perpetuity.¹⁷⁷</p> |
| <p>Tailings spills and impoundment failures</p> | <p>There have been multiple spills of tailings, releasing hazardous substances.</p> <p>The largest event occurred at the No. 3 tailings dam in 1980, spilling 2.6 million cubic yards of tailings into the Mangas Valley.¹⁷⁸ Tailings flowed 8 kilometers downstream and inundated farmland.¹⁷⁹ The failure occurred due to a dam wall breach.</p> <p>2001: 5 tons of tailings spilled into the Mangas Wash from the stormwater containment dike at the tailings dam.¹⁸⁰</p> <p>1990: Minor tailings spills from the No. 1 tailings pond in January 1990, and similar minor spills from the No. 2 tailings pond during 1990.¹⁸¹</p> |
| <p>Impacts to water, fish and wildlife</p> | <p>Streams and washes in the vicinity of the Tyrone Mine facility are ephemeral – they flow only after significant precipitation events.</p> <p>According to the 2003 preliminary assessment, “Surface water is exposed to hazardous substances released from the Tyrone Mine through a variety of pathways. Mangas Creek,</p> |

| | |
|--|--|
| | <p>an ephemeral stream adjacent to the Mine, which becomes perennial at Mangas Springs has been exposed to hazardous substances through spills and potentially through runoff and erosion.”¹⁸²</p> <p>The areal extent of the contaminated groundwater plume at the Tyrone Mine is 6,280 acres.¹⁸³ Groundwater seepage will require water treatment in perpetuity (see above).</p> |
|--|--|

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

| MIAMI MINE, AZ (Freeport McMoRan; formerly owned by Phelps Dodge and Cyprus Amax Minerals) The Miami Mine is an open pit mine located 90 miles east of Phoenix, Arizona. | |
|---|--|
| Reports of pipeline failures and other accidental releases* | 2011: Report of 1,600 pounds of sulfuric acid spilled from pipeline due to faulty weld. ¹⁸⁴ 2009: Report of 1,000 pounds of sulfuric acid spilled due to pipeline break. ¹⁸⁵ 2007: Report of a release of 9,450 pounds of sulfuric acid from pipeline. ¹⁸⁶ 2001: Report of a release of 153 pounds and 6.4 pounds respectively of lead/arsenic from pipeline. ¹⁸⁷ 2001: Report of a release of 2,070 pounds of acid plant blowdown from pipeline. ¹⁸⁸ 1997: Report of 10,000 gallons of copper sulfate due to overflow of tank. ¹⁸⁹ 1996: Report of 50,000 gallons of sulfuric acid due to tank failure. ¹⁹⁰ 1996: Report of 8,995 pounds of sulfuric acid due to leaky pipe. ¹⁹¹ |
| Water collection and treatment failures | The Pinal Creek drainage was designated a Water Quality Assurance Revolving Fund (WQARF) site by the Arizona Department of Environmental Quality in 1989 due to acidity and metals contamination in the alluvial aquifer. The WQARF program is the state equivalent of the Federal “superfund” program. The Miami Mine, inherited from the Cyprus Miami Mine (formerly the Inspiration Mine) is a member of the Pinal Creek Water Quality Assurance Revolving Fund (WQARF) Site. ¹⁹² The Pinal Creek site was listed under the Arizona Water Quality Assurance Revolving Fund program in 1989 for contamination in the shallow alluvial aquifers within the Pinal Creek drainage near Miami, Arizona. ¹⁹³ |
| Impacts to water, fish and wildlife | The Water Quality Assurance Revolving Fund (WQARF) program is the state equivalent of the Federal “superfund” program. The Miami Mine, inherited from the Cyprus Miami Mine (formerly the Inspiration Mine) is a member of the Pinal Creek Water Quality Assurance Revolving Fund (WQARF) Site. ¹⁹⁴ The Pinal Creek drainage was designated a WQARF site by ADEQ in 1989 due to acidity and metals contamination in the alluvial aquifer. ¹⁹⁵ |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

| SILVER BELL MINE, AZ (ASARCO) | |
|--|--|
| The Silver Bell Mine is an open pit copper mine located on the southern edge of the Silver Bell Mountains. | |
| Reports of pipeline failures and other accidental releases* | <p>2010: Report of 3,983 pounds of sulfuric acid released due to pipeline failure.¹⁹⁶</p> <p>2006: Report of 90,000 gallon release of raffinate; a mixture of 5.5 grams per liter of sulfuric acid and various metals. The release was due to equipment failure of a 24-inch mining pipeline.¹⁹⁷</p> <p>2002: Report of 242,000 pounds of process solution (with 1300 pounds of sulfuric acid) spilled due to power failure and overflow of solution pond.¹⁹⁸</p> |
| Water collection and treatment failures | <p>In 2009, Silver Bell was fined \$170,000 for three spills totaling 340,000 gallons of wastewater containing sulfuric acid and heavy metals into dry washes.¹⁹⁹ The pollutants seeped into soil, which endangered the groundwater in the aquifer below the mine and exceeded water quality standards. Two of the spills are described as such: Between Nov. 6 and Dec. 11, 2006, 150,000 gallons of leach solution containing sulfuric acid and metals escaped from a leaking impoundment. And between Nov. 11 and Dec. 13, 2006 another 100,000 gallons of stormwater containing sulfuric acid and heavy metals escaped from a storage pit.</p> <p>According to an EPA report, during site inspections of the mine in January and March 1993, the Arizona Department of Environmental Quality (ADEQ) observed water flowing in three unnamed washes below Silver Bell Mine.²⁰⁰ Samples taken from the two streams flowing under the waste rock dump showed violations of standards for total selenium, with one stream also violating standards for dissolved copper. The third stream, which flows from the leach dump, showed a broader range of exceedances, and concentrations of copper in this stream were several orders of magnitude greater than the concentrations in the other streams. Analyses showed violations of standards for pH, total zinc, total cadmium, and dissolved copper.</p> |
| Tailings spills and impoundment failures | Tailings spills (See below). |
| Impacts to water, fish and wildlife | According to a 2000 report on native fish populations by Pima County, "The loss of native fish along Cocio Wash is a good example of the potentially damaging effects that mining can have on aquatic ecosystems. Summer floods in July and August 1981 swept gray clay sediments from a Silverbell Mine tailings pond into the wash. BLM biologist Bill Kepner later reported, Our studies indicate that the Cocio Wash topminnow population is now extinct in that habitat due to recurrent mine spills and inundations by mine tailings... (Fonseca, 2000)." ²⁰¹ |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

| MINERAL PARK MINE, AZ (Mercator) | |
|---|---|
| Mineral Park is an open pit copper mine in the Cerbat Mountains near Kingman, AZ. | |
| Reports of pipeline spills and other accidental releases* | <p>1996: Report of 150 - 200 gallons of sulfuric acid released from acid storage tank due to equipment failure.²⁰²</p> <p>1996: Report of 200 gallons of sulfuric acid released.²⁰³</p> <p>1996: Report of 1,100 gallons of sulfuric acid spilled.²⁰⁴</p> |
| Water collection and treatment failures | <p>According to a 1995 report by the Arizona Geological Survey, water quality samples were taken of streamflow just below the Mineral Park mine and of mine water seeping through a dam at the southwest end of the tailings.²⁰⁵ Both samples showed extremely low pH values (3.2, 2.6), extremely high TDS values (5,549 and 6,625 mg/L) and extremely high sulfate contents (4,500 and 6,000 mg/L). According to the report, "the cadmium concentration of the stream flow just downstream of the Cyprus Mineral Park Mine place is 75.4 times higher than the standard, copper exceeds the standard 51 times and zinc 17.2 times." It further states that, "The discharge from the tailings ran down the washes until about two years ago, when the dam around the tailings was built. In years with very heavy rains the water could eventually reach the Sacramento Wash."²⁰⁶</p> <p>According to a 1999 EPA report, the Mineral Park Mine collected surface water samples from seven drainages and analyzed them for metals and radio-chemicals.²⁰⁷ All of these drainages, except for Golden Eagle Spring, exceeded either the federal Maximum Contaminant Levels (MCLs) and or state guidelines for gross alpha or gross beta. According to the report, "ADEQ observed that surface water runoff emanating from the drainages in the mine area were affecting the water quality of the alluvial pediment." Data showed that the plume contained high levels of beryllium, cadmium, fluoride and nickel. The report further stated that, "the data show that TENORM is discharging from abandoned mine adits and is impacting surface water and that mining operations have impacted groundwater."²⁰⁸</p> <p>A 2006 technical feasibility report commissioned by the company also describes a plume of contaminated groundwater migrating down-gradient from the mine.²⁰⁹</p> |
| Impacts to water, fish and wildlife | See above. |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

CONTINENTAL PIT MINE, MT (Montana Resources)

The Continental Pit is immediately adjacent to the Berkeley Pit in Butte Montana, and was initially known as the East Berkeley Pit. The Berkeley Pit and Continental Pit are included within the boundaries of the Silver Bow Creek/Butte Area Superfund site, which was established in 1983. Mining in the Berkeley Pit was discontinued in 1982, and in the East Berkeley Pit (now the Continental pit) in 1983. Mining was resumed in the Continental Pit by Montana Resources in 1986.²¹⁰ Because of their proximity, management of water and mine waste at the two mine sites are closely intertwined.

| | |
|---|---|
| <p>Reports of pipeline spills and other accidental releases*</p> | <p>On January 28, 2009, an incident was reported to the Department involving a broken tailings line while crews were doing maintenance. The cause was attributed to a tailings line that was plugged with ice and a weld broke. The water was shut off within five minutes and no water left the site or reached state waters.²¹¹</p> <p>1992: Department records show an accidental release of 0.34 million gallons in August of 1992.²¹²</p> |
| <p>Water collection and treatment failures</p> | <p>According to a 1993 report, the sources of groundwater contamination in the Butte Mine Flooding Operable Unit of the Superfund Site were identified as: the underground workings; the walls of the Berkeley and Continental Pits; mine water in the underground workings; waste rock and tailings piles near the Berkeley Pit; leaking solutions from the leach pad and the Weed/MR Concentrator areas; leaking solutions from the Yankee Doodle Tailings Pond; contaminated soils and alluvium, and sulfuric acid added to the underground mines for copper leaching. Sources of water containing hazardous substances include: 1) process solutions from the historic Weed Concentrator and the current MR Concentrator.²¹³</p> <p>Montana Resources suspended mining in the Continental Pit from 2000-2003 due to rising electricity costs.²¹⁴ During that time, about 7.5 billion gallons of water, or an average of 6 million gallons per day, went into the Berkeley Pit, to be combined with the highly acidic pit water already there. Montana Resources also diverted water from the Continental Pit into the Berkeley Pit for containment during their suspension. This contributed to increased water levels in the Berkeley Pit, and triggered the need to develop a water treatment plant to treat the contaminated water from the pit, which was rising to a critical level where contaminated pit water becomes an additional source of contamination to the surrounding aquifer and Silver Bow Creek. Under a consent decree with the State of Montana and US Department of Justice, a treatment plant was constructed and the mining companies are obligated to continue water treatment in perpetuity to prevent additional groundwater contamination.²¹⁵</p> <p>Mine tailings from the Continental Pit mine are placed in the Yankee Doodle tailings impoundment, which also contains the mine waste from previous mining at the Berkeley Pit. The tailings impoundment is unlined, and seepage from the impoundment travels through faults and fractures into the Berkeley Pit. When mining ceases, seepage from the tailings impoundment will continue to contribute contaminated water to the Berkeley pit. As noted above, a consent decree requires contaminated water from the Berkeley Pit to be collected and treated in perpetuity.</p> |

*Limitations in the data for pipeline spills and other accidental releases make it difficult to determine, in some cases, whether water quality impacts resulted from the spill.

REFERENCES

- ¹ Wanty, R.B., et al. "Environmental Behavior of several porphyry molybdenum and copper deposits in the western U.S.," Presented at the 4th European Congress on Geoscientific Cartography, Bologna, Italy, June 16-20, 2003., available at crustal.usgs.gov/projects/near_surface_processes/.../porphyry.pdf
- ² Kuipers, J.R., Maest, A.S., MacHardy, K.A., and Lawson, G. 2006. *Comparison of Predicted and Actual Water Quality at Hardrock Mines: The reliability of predictions in Environmental Impact Statements.*
- ³ US Geological Survey, 2010 Minerals Yearbook, Copper (Advanced Release), June 2012.
- ⁴ Freeport McMoran, 2011 Securities and Exchange Commission, Form 10-K.
- ⁵ Ibid.
- ⁶ Ibid.
- ⁷ Ibid.
- ⁸ Ibid.
- ⁹ US Geological Survey, 2010 Minerals Yearbook, Copper (advanced Release), June 2012.
- ¹⁰ Freeport McMoran, 2011 Securities and Exchange Commission, Form 10-K.
- ¹¹ <http://azgeology.azgs.az.gov/article/minerals-and-mining/2011/09/2010-arizona-mining-review>
- ¹² Ibid.
- ¹³ Ibid.
- ¹⁴ Ibid.
- ¹⁵ US Geological Survey, 2010 Minerals Yearbook, Copper, June 2012.
- ¹⁶ Arizona Dept. Of Environmental Quality, Press Release, "Freeport McMoran Morenci Inc. Agrees to \$150,000 Settlement to Resolve Water Quality Violations from 2008 Spill," July 14, 2011
- ¹⁷ National Response Center, Incident No. 835711
- ¹⁸ National Response Center, Incident No. 802300
- ¹⁹ ADEQ, Hazardous Materials Incident Logbook, Incident No. 99-005-B, <http://www.azdeq.gov/databases/hwssearch.html>
- ²⁰ National Response Center, Incident No. 791470
- ²¹ National Response Center, Incident No. 739154
- ²² ADEQ, Hazardous Materials Incidence Logbook, Incident No. 01-081-E
- ²³ ADEQ, Hazardous Materials Incidence Logbook, Incident No. 01-022-D
- ²⁴ ADEQ, Hazardous Materials Incidence Logbook, Incident No. 99-005-B
- ²⁵ National Response Center, Incident No. 356439
- ²⁶ National Response Center, Incident No. 318896
- ²⁷ National Response Center, Incident No. 341565
- ²⁸ ADEQ, Hazardous Materials Incidence Logbook, Incident No. 96-052-C
- ²⁹ ADEQ, Hazardous Materials Incidence Logbook, Incident No. 95-028-C
- ³⁰ National Response Center, Incident No. 240459
- ³¹ National Response Center, Incident No. 259755
- ³² National Response Center, Incident No. 205224
- ³³ National Response Center, Incident No. 198794
- ³⁴ National Response Center, Incident No. 134354
- ³⁵ National Response Center, Incident No. 134921
- ³⁶ National Response Center Incident No. 113212
- ³⁷ United States and State of Arizona v. Freeport McMoran Corporation and Freeport McMoran Morenci Inc, Consent Decree, Case 4:12-cv-00307-HCE, April 2012.
- ³⁸ Stratus Consulting Inc., "Preassessment screen for the Chino, Tyrone and Cobre Mines Prepared for the US Fish and Wildlife Services, June 18, 2003. p. 3-4.
- ³⁹ Stratus Consulting Inc., "Preassessment screen for the Chino, Tyrone and Cobre Mines Prepared for the US Fish and Wildlife Services, June 18, 2003. p. 5-7.
- ⁴⁰ Stratus Consulting Inc., "Preassessment screen for the Chino, Tyrone and Cobre Mines Prepared for the US Fish and Wildlife Services, June 18, 2003. p. 3-7.
- ⁴¹ US Department of Justice, Press Release: "Freeport-McMoran Corp and Freeport-McMoran Morenci Inc. will pay \$6.8 million in Damages for Injuries to Natural Resources from the Morenci Copper Mine in Arizona. April 24, 2012. <http://www.justice.gov/opa/pr/2012/April/12-enrd-527.html>
- ⁴² National Response Center, Incident Report No. 987867
- ⁴³ National Response Center, Incident Report No. 990280
- ⁴⁴ National Response Center, Incident Report No. 985090
- ⁴⁵ National Response Center, Incident Report No. 929521
- ⁴⁶ National Response Center, Incident Report No. 853889
- ⁴⁷ National Response Center, Incident Report No. 823579
- ⁴⁸ National Response Center, Incident Report No. 820928
- ⁴⁹ National Response Center, Incident Report No. 812340
- ⁵⁰ National Response Center, Incident Report No. 792304
- ⁵¹ National Response Center, Incident Report No. 738803
- ⁵² National Response Center, Incident Report No. 711893

-
- ⁵³ National Response Center, Incident Report No. 706853
- ⁵⁴ National Response Center, Incident Report No. 653465
- ⁵⁵ National Response Center, Incident Report No. 646582
- ⁵⁶ National Response Center, Incident Report No. 646700
- ⁵⁷ National Response Center, Incident Report No. 646508
- ⁵⁸ National Response Center, Incident Report No. 604649
- ⁵⁹ National Response Center, Incident Report No. 561032
- ⁶⁰ National Response Center, Incident Report No. 530556
- ⁶¹ National Response Center, Incident Report No. 537295
- ⁶² US EPA, Kennecott North, ROD, 2002. p. 129 of pdf.
- ⁶³ Ibid.
- ⁶⁴ US EPA, Kennecott North ROD, 2002, p. 205 of pdf.
- ⁶⁵ US EPA, ECHO.gov, Kennecott copper smelter & refinery, CWA/NPDES compliance status, Apr-June 2011 & Jul-Sept. 2011.
- ⁶⁶ <http://www.epa.gov/region8/superfund/ut/kennecottsouth/index.html>
- ⁶⁷ US EPA, Kennecott North ROD, September 2002.
- ⁶⁸ Richard Borden, et. al. "Groundwater response to the end of forty years of copper heap leach operations, Bingham Canyon Utah." Paper presented at the 7th International Conference on Acid Rock Drainage, March 26-30, 2006. Published by the American Society of Mining and Reclamation, 3134 Montavesta Road, Lexington, KY 40502. p. 231.
- ⁶⁹ United States v. Kennecott Utah Copper Corporation. Complaint Case: 2:08cv00122. February 14, 2008.
www.fws.gov/.../r_r_Kennecott_Utah_Copper_ComplaintFinal.pdf
- ⁷⁰ Ibid.
- ⁷¹ Ibid.
- ⁷² National Response Center, Incident Report No. 1013648
- ⁷³ ASARCO Press Release, "ASARCO Settles with ADEQ Over Tailings Spill," April 2010.
- ⁷⁴ Arizona Department of Environmental Quality, Notice of Violation for Case No. 79745, July 12, 2007.
- ⁷⁵ National Response Center, Incident Report No. 826624
- ⁷⁶ National Response Center, Incident Report No. 808478
- ⁷⁷ ADEQ Hazardous Incident Report Database, Incident No. 01-037-E
- ⁷⁸ ADEQ, Hazardous Incident Report Database, Incident No. 01-088-D
- ⁷⁹ ADEQ, Hazardous Incident Report Database, Incident No. 99-150-D
- ⁸⁰ State of Arizona and US Department of Interior, "Draft Restoration Plan and Environmental Assessment for the Hazardous Substance Releases from the Hayden Smelter and Ray Mine Facilities, February 2012. p. 3.
- ⁸¹ Ibid.
- ⁸² Ibid.
- ⁸³ US EPA, Damage Cases and Environmental Releases from Mines and Mineral Processing Sites, 1997. p. 65.
- ⁸⁴ Ibid.
- ⁸⁵ US EPA, Damage Cases and Environmental Releases from Mines and Mineral Processing Sites, 1997. p. 63
- ⁸⁶ Ibid.
- ⁸⁷ US EPA, Damage Cases and Environmental Releases from Mines and Mineral Processing Sites, 1997. p. 54
- ⁸⁸ Ibid.
- ⁸⁹ Ibid.
- ⁹⁰ Personal Communication, Peter Jagow, Compliance inspector, Arizona DEQ, July 10, 2012, based on February 2012 inspection.
- ⁹¹ Arizona Department of Environmental Quality, Notice of Violation, Case ID #130170, May 9, 2012.
- ⁹² National Response Center, Incident No. 975013
- ⁹³ Arizona Department of Environmental Quality, Inspection Report, May 6, 2011.
- ⁹⁴ US EPA, Damage Cases and Environmental Releases from Mines and Mineral Processing Sites, 1997. p. 59.
- ⁹⁵ Ibid.
- ⁹⁶ Ibid.
- ⁹⁷ State of Arizona and US Department of Interior, "Draft Restoration Plan and Environmental Assessment for the Hazardous Substance Releases from the Hayden Smelter and Ray Mine Facilities," February 2012.
- ⁹⁸ Ibid.
- ⁹⁹ Ibid.
- ¹⁰⁰ New Mexico Environmental Department, Press Release: Environment Department Reaches \$276,000 Settlement with Freeport McMoran Chino Mines Co. Regarding Acid Spill that Contaminated Groundwater in Silver City." April 17, 2009.
- ¹⁰¹ Stratus Consulting Inc., "Preassessment screen for the Chino, Tyrone and Cobre Mines Prepared for the US Fish and Wildlife Services, June 18, 2003. P. 2-13.
- ¹⁰² Stratus Consulting, "Preliminary Assessment Screen for the Chino, Tyrone and Morenci Mine Sites, Grant County, New Mexico and Morenci, Arizona," Prepared for US Fish and Wildlife Services, June 2003, p. 3-4.
- ¹⁰³ Stratus Consulting Inc., "Preassessment screen for the Chino, Tyrone and Cobre Mines Prepared for the US Fish and Wildlife Services, June 18, 2003. p. 51 of pdf.
- ¹⁰⁴ United States and State of New Mexico v. Freeport McMoran Corporations, et. al, Consent Decree, Case 1:11-cv-01140. December 2011.

- ¹⁰⁵ Stratus Consulting Inc., "Preassessment screen for the Chino, Tyrone and Cobre Mines Prepared for the US Fish and Wildlife Services, June 18, 2003. p. 3-3.
- ¹⁰⁶ Stratus Consulting Inc., "Preassessment screen for the Chino, Tyrone and Cobre Mines Prepared for the US Fish and Wildlife Services, June 18, 2003. p. 2-16.
- ¹⁰⁷ Stratus Consulting Inc., "Preassessment screen for the Chino, Tyrone and Cobre Mines Prepared for the US Fish and Wildlife Services, June 18, 2003. p. 2-18.
- ¹⁰⁸ New Mexico Office of Natural Resources Trustee, "Final Groundwater Restoration Plan for the Chino, Cobre and Tyrone Mine Facilities, January 4, 2012. p. 2-14.
- ¹⁰⁹ Stratus Consulting Inc., "Preassessment screen for the Chino, Tyrone and Cobre Mines Prepared for the US Fish and Wildlife Services, June 18, 2003.
- ¹¹⁰ New Mexico Office of Natural Resource Trustees, "Draft Groundwater assessment Restoration Plan for the Chino, Tyrone and Cobre Mines," September 2011. p. 5 of pdf.
- ¹¹¹ New Mexico Office of Natural Resources Trustee, "Final Groundwater Restoration Plan for the Chino, Cobre and Tyrone Mine Facilities, January 4, 2012. p. 2-14.
- ¹¹² National Response Center, Incident No. 922634
- ¹¹³ National Response Center, Incident No. 825857
- ¹¹⁴ National Response Center, Incident No. 743528
- ¹¹⁵ National Response Center, Incident No. 734733
- ¹¹⁶ National Response Center, Incident No. 476104
- ¹¹⁷ National Response Center, Incident No. 379507
- ¹¹⁸ National Response Center, Incident No. 403949
- ¹¹⁹ US EPA, press release, "Cyprus Bagdad to pay \$760,000 to settle water pollution charges," 9/16/1996.
- ¹²⁰ Ibid.
- ¹²¹ US EPA, Damage Cases and Environmental Releases from Mine and Mineral Processing sites, 1997.
- ¹²² Ibid.
- ¹²³ Kuipers, J.R., Maest, A.S., MacHardy, K.A., and Lawson, G. 2006. *Comparison of Predicted and Actual Water Quality at Hardrock Mines: The reliability of predictions in Environmental Impact Statements.*
- ¹²⁴ National Response Center, Incident No. 981624
- ¹²⁵ National Response Center, Incident No. 891124
- ¹²⁶ Arizona Department of Environmental Quality, Hazardous Materials Incidence Logbook, <http://www.azdeq.gov/databases/hwssearch.html>, Incident No. 06-019-J.
- ¹²⁷ ADEQ, Incident No. 06-019-J
- ¹²⁸ ADEQ, Incident No. 02-115-J
- ¹²⁹ ADEQ, Incident No. 02-007-J
- ¹³⁰ ADEQ, Incident No. 00-168-D
- ¹³¹ National Response Center, Incident No. 444403
- ¹³² ADEQ, Incident No. 98-047-B
- ¹³³ ADEQ, Incident No. 98-048-B
- ¹³⁴ National Response Center, Incident No. 394775
- ¹³⁵ National Response Center, Incident No. 382190
- ¹³⁶ National Response Center, Incident No. 327271
- ¹³⁷ US EPA, Damage Cases and Environmental Releases from Mines and Mineral Processing Sites, 1997, p. 173.
- ¹³⁸ Ibid.
- ¹³⁹ Ibid.
- ¹⁴⁰ Ibid.
- ¹⁴¹ Ibid.
- ¹⁴² US EPA, Damage Cases and Environmental Releases from Mines and Mineral Processing Sites, 1997, p. 173.
- ¹⁴³ Ibid.
- ¹⁴⁴ Martha Mottley, for Freeport McMoran, "Water Re-use for Managing Impacted Water at Sierrita Mine," Power Point Presentation, May 3, 2011.
- ¹⁴⁵ National Response Center, Incident No. 929841
- ¹⁴⁶ National Response Center, Incident No. 929371
- ¹⁴⁷ BHP Billiton, Follow-Up Report, Environmental Release, National Response Center, Letter to EPA, October 31, 2007.
- ¹⁴⁸ National Response Center, Incident No. 580872
- ¹⁴⁹ US EPA, Region 9, Total Maximum Daily Load for Copper into Pinto Creek, Arizona, April 2001. p. 11.
- ¹⁵⁰ Ibid. p. 14.
- ¹⁵¹ US EPA, Damage Cases and Environmental Releases from Mine and Mineral Processing sites, 1997. p. 32.
- ¹⁵² Ibid.
- ¹⁵³ US EPA, Region 9, Total Maximum Daily Load for Copper into Pinto Creek, Arizona, April 2001. p. 14.
- ¹⁵⁴ US Fish and Wildlife Service, Environmental Contaminants Program website, Pinto Creek Restoration, News and Activities, Arizona. Posted on December 22, 1999. Available at: <http://www.fws.gov/contaminants/DisplayNews.cfm?NewsID=E2D4E088-7448-11D4-A169009027B6B5D3>
- ¹⁵⁵ US EPA, Damage Cases and Environmental Releases from Mine and Mineral Processing sites, 1997. p. 35.

-
- ¹⁵⁶ Ibid.
- ¹⁵⁷ Ibid. p. 36.
- ¹⁵⁸ US EPA, Damage Cases and Environmental Releases from Mines and Mineral Processing Sites, 1997. p. 38.
- ¹⁵⁹ Ibid.
- ¹⁶⁰ National Response Center, Incident No. 986438.
- ¹⁶¹ National Response Center, Incident No. 565739
- ¹⁶² US EPA, ASARCO Mission Complex Fact Sheet: EPA PERMIT NO. AZ0024635, September 22, 2008.
- ¹⁶³ US Department of Interior, Bureau of Reclamation, San Xavier District Arroyos Recharge Project, Final Environmental Assessment, May 2009. p. 16.
- ¹⁶⁴ Ibid.
- ¹⁶⁵ US EPA, Damage Cases and Environmental Releases from Mines and Mineral Processing Sites, 1997, p. 170. The Robinson Mine was formerly owned by BHP Copper, Magma Nevada Mining Company.
- ¹⁶⁶ Nevada Department of Environmental Quality, Finding of Alleged Violation and Order, Robinson Operation, White Pine County, Nevada, April 2010.
- ¹⁶⁷ Associated Press, "Acid Spill Near Tyrone Cleaned Up" Albuquerque Journal, November 10, 2006. Available at: <http://www.abqjournal.com/news/state/apspill11-10-06.htm>
- ¹⁶⁸ National Response Center, Incident No. 649767
- ¹⁶⁹ Ibid.
- ¹⁷⁰ Stratus Consulting, Preassessment Screen for the Chino, Tyrone, and Morenci Mine Sites, Grant County, New Mexico, and Morenci, Arizona, Prepared for US Fish and Wildlife Service, June 18, 2003. p. 2-15.
- ¹⁷¹ Ibid. p. 2-14.
- ¹⁷² Ibid. p. 2-15.
- ¹⁷³ New Mexico Office of Natural Resources Trustee, "Final Groundwater Restoration Plan for the Chino, Cobre and Tyrone Mine Facilities, January 4, 2012. p. 2-15.
- ¹⁷⁴ United States and State of New Mexico v. Freeport McMoran Corporations, et. al, Consent Decree, Case 1:11-cv-01140. December 2011.
- ¹⁷⁵ Stratus Consulting, Preassessment Screen for the Chino, Tyrone, and Morenci Mine Sites, Grant County, New Mexico, and Morenci, Arizona, Prepared for US Fish and Wildlife Service, June 18, 2003.
- ¹⁷⁶ Stratus Consulting, Preassessment Screen for the Chino, Tyrone, and Morenci Mine Sites, Grant County, New Mexico, and Morenci, Arizona, Prepared for US Fish and Wildlife Service, June 18, 2003.
- ¹⁷⁷ New Mexico Office of Natural Resources Trustee, "Final Groundwater Restoration Plan for the Chino, Cobre and Tyrone Mine Facilities, January 4, 2012. Table 2.1. p. 2-14.
- ¹⁷⁸ Stratus Consulting, Preassessment Screen for the Chino, Tyrone, and Morenci Mine Sites, Grant County, New Mexico, and Morenci, Arizona, Prepared for US Fish and Wildlife Service, June 18, 2003. Table 2.3. p. 2-11.
- ¹⁷⁹ World Information Service on Energy (WISE) Uranium Project, Chronology of Major Tailings Dam Failures, website available at: <http://www.wise-uranium.org/mdaf.html>
- ¹⁸⁰ Stratus Consulting, Preassessment Screen for the Chino, Tyrone, and Morenci Mine Sites, Grant County, New Mexico, and Morenci, Arizona, Prepared for US Fish and Wildlife Service, June 18, 2003. p. 2-11.
- ¹⁸¹ Ibid.
- ¹⁸² Ibid. p. 3-6.
- ¹⁸³ New Mexico Office of Natural Resources Trustee, "Final Groundwater Restoration Plan for the Chino, Cobre and Tyrone Mine Facilities, January 4, 2012. p. 3-18.
- ¹⁸⁴ National Response Center, Incident No. 1001170
- ¹⁸⁵ National Response Center, Incident No. 916652
- ¹⁸⁶ National Response Center, Incident No. 849665
- ¹⁸⁷ Arizona Department of Environmental Quality, Hazardous Materials Incidence Logbook, Incident No. 01-200-B
- ¹⁸⁸ ADEQ, Incident No. 01-183-B
- ¹⁸⁹ National Response Center, Incident No. 383245
- ¹⁹⁰ National Response Center, Incident No. 367631
- ¹⁹¹ National Response Center, Incident No. 356429
- ¹⁹² <http://www.g-a-l.info/AttachmentFour.htm>
- ¹⁹³ Ibid.
- ¹⁹⁴ <http://www.g-a-l.info/AttachmentFour.htm>
- ¹⁹⁵ Ibid.
- ¹⁹⁶ National Response Center, Incident No. 942625
- ¹⁹⁷ ADEQ, Press Release: Silver Bell Mining to Pay \$170,000 in civil penalties for water quality violations in Pima County. April 7, 2009.
- ¹⁹⁸ National Response Center, Incident No. 630005
- ¹⁹⁹ ADEQ, Press Release: Silver Bell Mining to Pay \$170,000 in civil penalties for water quality violations in Pima County. April 7, 2009.
- ²⁰⁰ US EPA, Damage Cases and Environmental Releases from Mines and Mineral Processing Sites, 1997. p. 23.
- ²⁰¹ Pima County, Arizona Board of Supervisors, Historical Occurrence of Native Fish in Pima County, December 2000. p. 19.
- ²⁰² National Response Center, Incident No. 356225
- ²⁰³ ADEQ, Hazardous Materials Incident Logbook, 96-067-C
- ²⁰⁴ ADEQ, Hazardous Materials Incident Logbook, 96-088-C

-
- ²⁰⁵ Arizona Geological Survey, Contributed report 95-1, Water Quality Investigations in the Historic Mining District of Chloride and Adjacent Areas in the Cerbat Mountains (Mojave County, AZ), December 1995. p. 19.
- ²⁰⁶ Ibid. p. 20.
- ²⁰⁷ US EPA, Technologically Enhanced Naturally Occurring Radioactive Materials in the Southwestern Copper Belt of Arizona, October 1999. p. 55.
- ²⁰⁸ Ibid. p. 58.
- ²⁰⁹ Range Consulting Group, LLC, "Technical Report Preliminary Feasibility on Phase I and Phase II Copper-Moly Milling Expansion Mineral Park Mine, Mohave County, Arizona. December 2006. p. 17.
- ²¹⁰ Maest, Ann S. and John J. Metesch, Butte Groundwater Injury Assessment Report, Clark Fork River Basin NPL Sites, Montana, Prepared for the State of Montana Natural Resources Damage Program, April 1993.
- ²¹¹ Montana Department of Environmental Quality, MPDES Permit Fact Sheet, Permit No. MT0000191, May 2012
- ²¹² Ibid.
- ²¹³ Maest, Ann S. and John Metesch, Butte Groundwater Injury Assessment Report, Clark Fork River Basin NPL Sites, Prepared for the State of Montana Natural Resources Damage Program, April 1993. p. 2-1.
- ²¹⁴ US EPA, Third Five-Year Review Report for Silver Bow Creek Butte Area, Butte Mine Flooding Operable Unit, June 2011
- ²¹⁵ Ibid.